

University of Minnesota Duluth

STORM WATER INSPECTION FORM

Outfall # : _____ Photograph Name : 03-ST4596- Inspection Date: 11/19/2003
 Pond Name: N/A
 Mechanical Structure # : ST4596 Type: Storm Cepter 900
 Location: Lot G
 Inspector: Erik J. Larson
 Weather: Air Temperature: 30 degrees Rain: Y N Date of Last Rain: 11/19 A.M. Sunny Cloudy
 Describe drainage area: North 1/2 of Lot G - Prior to underground storage system
 Shared Use: Y N Describe: _____

Physical Observations

Odor: None Sewage Sulfide Oil Gas Rancid-Sour Other: _____
Color: None Dark Brown Light Brown Other: _____
Turbidity: None Cloudy Opaque
Deposits / Stains: None Sediment Oily Describe: Sludge Sample Collected: Y N
 Depth of Sediment: N/A Measurement: < 1" Remaining Capacity _____
 Describe Work Needed: N/A None
Floatables: None Sheen Foam Sewage Litter Other: _____ Sample Collected: Y N
 Oil in Oil Port: Y N N/A Measurement: None Detected Calculated: _____
 Describe Work Needed: N/A
Vegetation Conditions: N/A Normal Excessive Growth Inhibited Growth Describe: _____
 Describe Work Needed: N/A
Erosion: None Minor Erosion Major Erosion Erosion Protected Y N
 Describe Work Needed: N/A
Condition: Good Average Poor Work Needed: Y N
 Describe Work Needed: N/A _____
Flow: Size of Pipe: _____ Depth of Water: 5' Has Source of Flow Been Determined: Y N
 Source of Water: N/A North 1/2 of Lot G - Feeds underground storage/WBTC
Water Temperature: _____ F Not Available

Inspection Comments / Recommendations

Comments / Recommendations	Completed	Date
New Construction Summer 03	Y N	_____
~Stormceptor has filled	Y N	_____
~Minor suspended solids in bottom of tank	Y N	_____
Depth of bottom of tank is 9'6" to north side of rim	Y N	_____
(nearest to oil port/through oil port)	Y N	_____
_____	Y N	_____
_____	Y N	_____

- MPCA Permit Requirements (Annual)
 Section V.G.6.b.2-6
- * Inspection of structural pollution control devices
 - * Inspect 20% of outfalls and ponds
 - * Note repair, replacement, and/or maintenance ne including schedule for completion
 - * Summarize inspection results for annual report

