

UMD 501 Impervious Surface Review FM Areas

Removal of Unneeded Impervious Surface



- Removed unusable exercise area and reseeded (2950 Sq. Ft)
- Removed two walks and replaced with one and plantings (1500 Sq. Ft.)