

Additional MP Summary Sheet

MS4 Name: University Minnesota Duluth

Minimum Control Measure: 6-POLLUTION PREVENTION/GOOD HOUSEKEEPING

Unique BMP Identification Number: 6a-3 (Revised 2007)

<p>*BMP Title: Exterior Loading Docks</p>
<p>*BMP Description:</p> <p>Identify loading and unloading procedures for liquid and particulate materials at all <u>exterior</u> loading docks.</p> <p>Location(s) in SWPPP of detailed information relating to this BMP: This summary sheet details all SWPPP information for this BMP. Related Information in 6a-1 / 6b-4</p>
<p>*Measurable Goals:</p> <p>Identify exterior loading areas and entities involved Review loading and unloading practices with departments that use these areas Make recommendations for storm water protection Develop procedures Develop training Implement procedure</p>
<p>*Timeline/Implementation Schedule:</p> <p>Identify exterior loading areas and entities involved – Done 2007 Review loading and unloading practices with departments that use these areas -2008 Make recommendations for storm water protection - 2008 Develop procedures - 2008 Develop training - 2009 Implement procedure - 2009 Review Procedure and make necessary modifications - 2010</p>
<p>Specific Components and Notes:</p> <p>Develop procedures for loading/unloading particulate materials. Develop procedures for loading docks regarding loading and unloading of liquid materials at all exterior docks. Provide training information regarding loading and unloading of liquid particulate materials. Departments will be made aware that they are responsible for following the final procedures</p>
<p>*Responsible Party for this BMP:</p> <p>Name: Erik Larson Department: Facilities Management Phone: 218-726-6915 E-mail: elarson@d.umn.edu</p>

**Indicates a REQUIRED field. Failure to complete any required field will result in rejection of the application due to incompleteness.*